


NATE'S

DRYER VENT CLEANING



(321) 872-7782
NATESDRYERVENTCLEANING.COM



VETERAN
OWNED BUSINESS

Who: Nathan Cox Owner/ Operator, Army Veteran with 3rd Infantry Division

What: Nate's Dryer Vent Cleaning is a **full service dryer vent company.**

- We offer the full cleaning package which dryer manufacturers recommend which includes thorough inspection of vent & dryer, disassembly of dryer for through interior cleaning, cleaning the vent, pre/post cleaning air pressure test
- Vent repairs
- Dryer Vent re-routes/ full installations (that are code compliant)
- Installation of other products that optimize dryer performance & safety

Our reputation is everything and our reviews validate we aim for and deliver elite customer service & workmanship.

We take integrity seriously, you won't have to worry about things such as: Did the work actually get done? Did the work get done right? Am I being scammed or taken advantage of? Are they trying to sell me something I don't need?

We are absolutely committed to integrity, transparency, accountability, communication and customer satisfaction

When: Started in the trade in June 2013

Where: Mechanicsville, Virginia (Richmond area)

How: Trained by owner of Clean Vent Dryer Exhaust Specialist, whom has his CDET (CDET= Certified Dryer Exhaust Technician – optional cert that I'm in the process of getting)

Why: I love this line of work because I get to meet new people every day and it gives me an outlet to do what I enjoy, troubleshoot, problem solve & serve/ help people.





Tips & Info

From FEMA's Website:

From 2008-2010 report

Facts about home clothes dryer fires

- 2,900 home clothes dryer fires are reported each year and cause an estimated 5 deaths, 100 injuries, and \$35 million in property loss.

- Failure to clean the dryer (34 percent) is the leading cause of home clothes dryer fires.



Prevent clothes dryer fires.

Clean lint filters every time you use the dryer. Clean your dryer vent ductwork every year.



More info..

From the National Fire Protection Agency's website:

Report highlights

- In 2010-2014, U.S. fire departments responded to an estimated average of 15,970 home structure fires involving clothes dryers or washing machines each year.
- These fires caused annual averages of 13 civilian deaths, 444 civilian injuries, and \$238 million in direct property damage.
- According to the NFPA Dryer Fires are the 6th Leading Cause of House Fires, just behind Arson.



Awards, Credentials & Memberships



Memberships

- Space Coast Communities Association (SCCA)
- Space Coast Association of Realtors (SCAR)
- National Fire Protection Agency (NFPA)
- Non-Paying Member of BBB w/ -> A+ Rating
- Former 2yr Member of BNI (Bus. Networking Int.)

Awards

- NextDoor "Neighborhood Fave" 3x
- Nearing 600 Review Reviews 99% of which is 5-Stars

Nate's Dryer Vent Cleaning

5.0 ★★★★★ 583 Google reviews ⋮

Dryer vent cleaning service



Awards, Credentials & Memberships Cont.

Credentials



- Certified Dryer Exhaust Technician (C-DET) Certified by Chimney Safety Institute of America (CSIA) (All Technicians)
- A Junior Instructor w/ CSIA & recently contributed 2 chapters to the updated Training C-DET Service Manual.
- Also have been a repeated special instructor with Inovate's recurring "Best Practice Summit" teaching dryer vent techs the importance of dryer clean outs and the HOW to.
- Have had consulted with dozens of other companies & have trained at least a half a dozen other technicians from other companies or whom were starting their own business.



Awards, Credentials & Memberships Cont.



NATE'S
DRYER VENT CLEANING

(321) 872-7782
NATESDRYERVENTCLEANING.COM



Credentials



Chimney Safety Institute of America



#1479
Valid Thru
July



2024

Nathan Cox
Nate's Dryer Vent Cleaning

Cocoa FL

www.CSIA.org

Chimney Safety Institute of America



#1492
Valid Thru
August



2024

Connor Bell
Nate's Dryer Vent Cleaning

Cocoa FL

www.CSIA.org

Chimney Safety Institute of America
Certified Dryer Exhaust Technician



#2011
Valid Thru
March 2027

Adam Vasquez
Nate's Dryer Vent Cleaning


Cocoa, FL

www.CSIA.org

Most Recently Published C-DET Manuals I helped Contribute To



Inovate's Best Practice Summit, Jupiter, FL



Vent Cleanings



Video of Dryer
Vent Cleaning



Place dryer at least 18 inches (460 mm) above the floor for a garage installation.

Failure to do so can result in death, explosion, or fire.

Keep dryer area clear and free from items that would block the airflow for proper dryer operation. This includes clearing piles of laundry in front of the dryer.

Cleaning the Dryer Interior

To clean dryer drum:

Dryer Cabinet Cleanout



2. Push the lint screen firmly back into place.


IMPORTANT:

- Do not run the dryer with the lint screen loose, damaged, blocked, or missing. Doing so can cause overheating and damage to both the dryer and fabrics.
- If lint falls off the screen into the dryer during removal, check the exhaust hood and remove the lint. See "Venting Requirements" in the Installation Instructions.
- Clean space where lint screen is located, as needed. Using a brush that has accumulated outside

er residue can build up on the longer drying times for your before your load is completely if lint falls off while the screen with a nylon brush every becomes clogged due to a

LA S
UAT
Une se
ment
dans l
d'écha
du pers

fingers.
th hot water.
er and liquid detergent. Scrub
move residue buildup.



4. Rinse screen with hot water.
5. Thoroughly dry lint screen with a clean towel. Reinstall screen in dryer.

Video of Dryer
Clean Out



*Video of Dryer
Clean Out*



Common Stock Cleaning



Bird Nest Removal




Birds...



*Things we find
In the course
Of our
inspection(s)*



*Things we find
In the course
Of our
inspection(s)*



**BIGGEST PIECE OF BURNT LINT
I'VE EVER PULLED FROM A
DRYER. THIS DRYER IS A 10 ON A
1-10 SCALE**

📍 MELBOURNE, FLORIDA

*Things we find
In the course
Of our
inspection(s)*



Significant amount of lint in this dryer, including a lot of burnt lint...

Things we find In the course Of our Rooftop inspections



Generic “goose-necks” commonly are problematic because they often accumulate lint and subsequently clog up.

This is what happens with generic hoods that are NOT designed for dryer vents (and no longer meet code)



*Things we find
In the course
Of our
inspection(s)*



*Things we find
In the course
Of our
inspection(s)*



*Things we find
In the course
Of our
inspection(s)*



*Things we find
In the course
Of our
inspection(s)*



Murray Ashman

3 hrs • 🌐



Anyone else's dryer vent clogged?



Vent Installations



Vent Installations



Vent Installations



Consequences of Clogs

- Long Dryer Times (increased energy cost)
- Overheating Dryer (Additional Consequences)
- Condensation & Water Accumulation (leaking vents)
- Expedited Accumulation of Lint in Dryer (dangerous dryers)

Consequences of Clogs



Consequences of Clogs





Flexible & Tough | Safe & Efficient

The DryerFlex Story

Venting Safety

Duct Comparison

Media


Get DryerFlex

Products we sell & install

Easy to Handle and Always 4"



As workable as "slinky" foil.




As efficient as semi-rigid



The Safest Transition Hose

DryerFlex vs "Slinky" Foil



Flame resistant unlike "slinky" foil.

Crush resistant unlike semi-rigid



Products we sell & install

Efficiency Matters

The termination is a very important part of the exhaust system. Restriction can dramatically reduce a dryer's ability to vent safely.

Every year, there are thousands of dryer fires across North America. Lint buildup is a major contributing factor. Eliminating restriction-points in the exhaust helps improve safety. It also helps save money on power bills with shorter drying times.



Efficient Dryer Roof Vent

[Roof Venting](#)

[Airflow Efficiency](#)

[Roof Vent Advantages](#)

[Specs & Installation](#)

[Locator](#)

Safe & Efficient Roof Venting

DryerJack® is engineered specifically for the demanding requirements of roof venting a dryer.

Airflow Efficient

Pest & Weatherproof

Code Compliant



Finally a Code Compliant Choice

One of the biggest contributors to dryer lint fires is vent restriction. Because code forbids the use of screens *and* requires a damper for dryer exhaust, installers previously had to alter the vent and / or settle for bad performance.

Today, you have a code compliant option right out of the box.



Products
we sell & install

DryerWallVent®



Premium Grade Vent Closure

Wall Vent Intro

Venting Efficiency

Product Advantages

Specs & Installation

Locator




Stylish ♦ Rugged ♦ Efficient

Designed to minimize airflow restriction, DryerWallVents™ are safe for dryer venting. Their low profile design and powder coated Galvalume® steel construction make a nice contribution to every home's beauty.



Be sure to showcase your vent installation as a premium grade component. It's a strong selling point that shows home buyers their new house is well made.



DWV4 Specifications

- ▶ Heavy Gauge Galvalume® Steel Body
- ▶ PPG Envirocron® Powder Coating in White, Tan or Brown
- ▶ Lighter Weight Galvalume® Damper (Lighter to Minimize Restriction)
- ▶ Intrusion Prevention Balanced Damper Magnets
- ▶ Quiet Closing Rubber Damper Bumpers
- ▶ Can Be Used for 70 CFM or Higher **Bath Vents**

Superior Pest Protection

The DEFENDER

Products we sell & install












-  Powder-Coated Steel
-  Helps Keep Animals Out
-  Allows Lint To Pass Through















★ Made In The USA ★

The Defender

Traditional Vent Guards

-  Zinc coated steel with a powder coated finish helps stand the test of time.
-  Vertical bars allow lint to pass through while birds and squirrels cannot come in.
-  Metal cannot be broken off or eaten by various critters.
-  Hooded design allows for additional weather protection.
-  Powder coated color options help match the existing siding to maintain exterior aesthetics.
-  Various sizes cover 3", 4", 5" and 6" vents.
-  Numerous mounting options are available.
-  Installs easily on all siding types.
-  Easily removable for duct cleaning and re-installation.


-  Plastic vent covers deteriorate from UV rays.
-  Cross bars block lint at a rapid rate, making the dryer vent far less efficient.
-  Plastic materials are susceptible to critter entry.
-  Accessible grates allow rain/snow to enter the covers which turns lint into a thick papier-mâché like barrier.
-  Standard white plastic often does not match and creates a dull, unsightly finish over time.
-  Standard sizes only cover 4" vents.
-  Single mounting method required.
-  Installs on limited amounts of siding materials.
-  Plastic materials may fall apart upon re-installation.
-  Unsightly vents remain visible.
-  Softer plastics break, bend, warp, and crack over time.
-  Cheaper solution that is often replaced.

*We install more than
mentioned
Feel free to inquire about
Other products we offer!*



Code compliant
or not, critter
guards will
ALWAYS have
the need to be:

- Accessible
- Inspectable
- Cleaned/
Maintained.



*Thanks
For
Tuning in!*

&

*Thank
YOU for
your
continued
support!*

